

M/051/0015



Leslie Heppler &lt;lheppler@utah.gov&gt;

7245

## Heber Binggeli Quarry NOI

1 message

**Dalley, Mike (Staker & Parson)** <Mike.Dalley@stakerparson.com>

Thu, Mar 3, 2016 at 4:42 PM

To: "Paul Baker (paulbaker@utah.gov)" &lt;paulbaker@utah.gov&gt;

Cc: "Leslie Hepler (lheppler@utah.gov)" &lt;lheppler@utah.gov&gt;

Paul,

I'm going through the DOGM comments for Heber Binggeli and I have the following questions:

- Comment 7 – What do you mean by Figure 2?
- Comment 13 – What is your reasoning to include the ready mix plant and maintenance facilities in the NOI? I feel they should not be included because they can operate without the mining operation. They are separate operations, much like the asphalt plant segregation was allowed at Keigley Quarry.
- Comment 19 – It states "Based on photos from the area, there should be more than six inches of topsoil available to deposit". How can you determine the amount of topsoil by a photograph? Please refer me to the photos that indicate the level of topsoil. Also stated in the comment was "2 samples are not sufficient". How many do you recommend? Also "not all samples need to be analyzed" was stated in the comments. If this is the case then why get more than the 2 samples already obtained if they don't need to be analyzed? What is the purpose of gathering samples?
- Comment 27 (same as comment 13)(the 2<sup>nd</sup> 27 on page 7 of the comments) – Please give reasoning behind the needed demolition of these items listed in table 3. These facilities are capital investments not tied to the mining operation.

Thanks,

Mike Dalley

### Staker Parson Companies

Oldcastle Mountain West Division Sustainability Director

801-455-7577